


INSTRUCTIONS for ATTACHING RACK MOUNT ADAPTOR BRACKETS (Bryston Part Number 271020)


to BP26 Preamps, MPS2 Power Supplies & 10B Crossovers

WARNING! Before installing the Rack Mount Adaptor Brackets, disconnect the power cord and all other interconnect cables from the BP26, MPS2 or 10B to which the brackets are being attached.

After disconnecting all cables from the preamp, crossover or power supply, remove the two front-most screws from each side of the top cover. If the screws are damaged in any way, do not reuse them. New screws are provided with the Rack Mount Adaptor Brackets should they be necessary. These screws are Robertson (square socket), undercut flat-head, 1/4" long steel #6-32 machine screws.



Attach the Rack Mount Adaptor Brackets using the same #6-32 screws that were removed from the top cover side panels. If these original screws were damaged, use the new screws provided with the brackets. Be careful not to over-tighten the screws.



preamp-rack-adaptor-instructions_20050401 